

LAND CORNER RECORD

Index: R-15	Corner: 1/4 Corner between Sections 22 and 27	State of Indiana - Hoosier National Forest
Section: 27	Township: 7N Range: 1E P.M.: 2nd	County: Monroe
Coordinate:	Lat./N: 1374372.853 Long./E: 3147837.215	Datum: NAD83 IN West Zone, US Survey Feet


CORNER HISTORY: (Chronological history of corner)

1.) Date of Survey:	Surveyor:	Monument:	Recording Information:	Monument Photograph:
5/14/1974	Andrew Sobiech L.S. #80040143	A 2" iron pipe with a stamped 3" brass cap set	USDA Forest Service Bedford, IN	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	Beech	12"	N40°E	25.00'
	Beech	12"	S50°E	4.60'
	Beech	12"	S48°W	13.60'
Record evidence of prior survey:	A 4"x4" post is N82°E - 8.30'.			
2.) Date of Survey:	Surveyor:	Monument:	Recording Information:	
11/10/2009	Kevin Enright Monroe County Surveyor	A 2" iron pipe with a stamped 3" brass cap found	Monroe County Surveyor's Office Bk. 41, Pg. 71	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	Beech	16"	N50°E	24.79'
	Beech	18"	S33°E	4.33'
	Wood Post	4"x4"	N89°E	8.24'
Record evidence of prior survey:				

ACCESSORIES: Bearing and distance from monument to witness object.

Reference Objects:	Object or Tree Species:	Diameter:	Bearing:	Distance:
	Beech**	14"	N50°E	24.71'
	Beech**	16"	S45°E	4.60'
	Wood Post	4"x4"	S85°E	9.00'
	Beech**	21"	S80°W	15.68'
Monument Found or Set:	An iron pipe with a 3" brass cap stamped "T7N R1E 1/4 S.22 S.27 1974 S.O. 143" found 0.6' above grade.			


MONUMENT SKETCH



NARRATIVE REFERENCE:

Monument is an iron pipe with a 3" brass cap stamped "T7N R1E 1/4 S.22 S.27 1974 S.O. 143" found 0.6' above grade, a carsonite post is located 1.0' north of the monument, located on the north face of a steep ravine, +/- 30' south of the centerline of a drainage, +/- 150' north of a meandering trail on a ridge top, surrounded by mature forest, monument had been uprooted and was falling down the hill, it was reset using the previous bearing trees.

SECTION DIAGRAM



Corner Location = ●

PERPETUATION RECORD:

The record monument was found disturbed and reset using two previous bearing trees and maintained by remarking the existing bearing trees and establishing one new bearing tree. Two existing bearing trees and one existing reference object were recovered from a Monument Record by Kevin Enright, dated 11/10/2009.

One new bearing tree was marked with a blaze, scribed B.T., bearing tree sign, paint, and mag nail.

Referenced on BRCJ survey recorded as InstNo.2018007752

Accepted by the Monroe County Surveyor Review Board on August 6, 2019.

Section: 27 T7N R1E


Prepared By: BRCJ (Project#3-0822) Date: 5/2018

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 27 Township: 7 North Range: 1 East Corner ID: Polk O-17

Monument Description & Remarks: 3" Brass Disk stamp. "T7N R1E, S.22/S.27, 1/4, 1974 SO143".
Survey Sign 2.5ft above ground at pt. C

References On File: Andrew J. Sobiech, Certified Land Corner Restoration (1974), on file in
Surveyor Office




I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 22nd day of October, 2008

Kevin Enright

Administered by the Monroe County Surveyor Review Board

Date: 11/10/2009



✓ A.M. _____ P.M. 2:34 ✓

MAR 18 1985

168716

✓ *Thomas J. Hanson*
RECORDER MONROE CO., IN ✓

155 PAGE 528

RD-5680-14 (5/1/64) H. C. MILLER CO., MILWAUKEE 447802

CERTIFIED LAND CORNER RESTORATION

0-17

State of Indiana }
County of Monroe } ss.

I, Andrew J. Sobiech, do hereby certify that on the 14 day of May, 19 74,
I found evidence of the 1/4 Section corner of Section 22-27
Township 7 North, Range 1 East, Second Principal Meridian, as described
hereon; and that from this evidence I established a new monument and accessories as described hereon to per-
petuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Original monument was
a wood post set in 1814.
Original bearing trees:
W. Oak W. Oak
8" 8"
S 33 E N 4 W
22 lks 22 lks

Description of corner evidence found:


Found sandstone 6"x3" 8" above ground at the base of old stump. Stone is marked
on top with + and a fence from east and west and south intersection at stone.

Description of monument and accessories I established to perpetuate the original location of this corner:

I replaced the stone with a 2" diameter by 3 ft. long concrete filled galvanized
iron pipe, capped with a 3" Di. brass tablet stamped to identify the corner. I
established the following witnesses:

Beech	4"x4" Post	Beech	Beech
12"	N 82° E	12"	12"
N 40° E	8.3 feet	S 48 W	S 50 E
25.0 feet		13.6 feet	4.6 feet

I laid the old stone on top of ground beside new monument.



Field Assistant
~~Resident witnesses~~ Henry Deaton - Tom Getz - USEFS
Dated at Brownstown Indiana, this 14 day of May
19 74.
Signature Andrew J. Sobiech Title R.L.S.
(County Surveyor, Registered Land Surveyor, or other duly authorized official)
Surveyors Registration No. S-0143
Office of _____ County of _____
I hereby certify that the within instrument was filed in this office for record
on the _____ day of _____ 19 _____, and was filed in Book
No. _____ Page No. _____ of County Records.
Signature _____ Title _____

CERTIFIED LAND CORNER RESTORATION

State of Indiana

County of Monroe

ss.

[0-17]

I Andrew J. Sobiech, do hereby certify that on the 14 day of May, 19 74,
I found evidence of the 1/4 Section corner of Section 22-27
Township 7 North, Range 1 East, Second Principal Meridian, as described
hereon; and that from this evidence I established a new monument and accessories as described hereon to per-
petuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Original monument was
a wood post set in 1814.

Original bearing trees:

W. Oak	W. Oak
8"	8"
S 33 E	N 4 W
22 lks	22 lks

Description of corner evidence found:


Found sandstone 6"x3" 8" above ground at the base of old stump. Stone is marked
on top with + and a fence from east and west and south intersection at stone.

Description of monument and accessories I established to perpetuate the original location of this corner:

I replaced the stone with a 2" diameter by 3 ft. long concrete filled galvanized
iron pipe, capped with a 3" Di. brass tablet stamped to identify the corner. I
established the following witnesses:

Beech	4"x4" Post	Beech	Beech
12"	N 82° E	12"	12"
N 40° E	8.3 feet	S 48 W	S 50 E
25.0 feet		13.6 feet	4.6 feet

I laid the old stone on top of ground beside new monument.



Field Assistant

~~Resident witnesses~~ Henry Deaton - Tom Getz - USFS


Dated at Brownstown Indiana, this 14 day of May
19 74.

Signature Andrew J. Sobiech Title R. L. S.
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Index No. R-15
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 7N R. 1E Mer. N.F. Hoosier County Monroe State Ind.
W Section Corner common to sections 22 27 and

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1814</u>		Year of search <u>1973</u>	By <u>H. Boston</u>
Original monument <u>Wood post</u> (Wood post, stone, pile of stones, pipe, etc.)		Monument found	
Bearing Trees Species <u>W. Oak</u> <u>W. Oak</u> Diameter <u>8"</u> <u>8"</u> Bearing <u>S33E</u> <u>N4W</u> Distance <u>22 1/2</u> <u>22 1/2</u>		Original Bearing Trees Found Species _____ Diameter _____ Bearing <u>None</u> Distance _____	
Subsequent Corner Restoration Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ (Original, concrete post, iron rod, etc.)		Evidence of Subsequent Corner Restoration Found Year of search <u>1973</u> By <u>H. Boston</u> <u>found 52nd one</u>	
Bearing Trees, Reference Objects Species _____ Diameter _____ Bearing _____ Distance _____		Bearing Trees, Reference Objects _____ _____ _____ _____	



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. found 52nd one on old fence running E-W-S 6" x 3"-8" above ground at the base of old stump.

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Remnant corner

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

At time of search:

1. Did you have the record description?

Yes ☒ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search 1 hr.4. Do you think additional search might recover evidence? Yes ☒ No _____5. Signature H. Boston